
Internal Photographs RF PCB Front without shields



RF PCB Back



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Phone/Fax: (913) 837-321 Revision 1 Lectrosonics, Inc. Model: HML Test #:090318L

Test to: FCC Parts 2 and 74, RSS-123


File: IntPho HML

FCC ID#: DBZHML 8024A-HML SN: 22


Page 1 of 2

Date: March 27, 2009

Digital PCB Front



Digital PCB Back



Rogers Labs, Inc. 4405 W. 259th Terrace Louisburg, KS 66053 Phone/Fax: (913) 837-3214

Revision 1

Lectrosonics, Inc. Model: HML Test #:090318L

Test to: FCC Parts 2 and 74, RSS-123

File: IntPho HML

FCC ID#: DBZHML 8024A-HML SN: 22

Page 2 of 2

Date: March 27, 2009