



3 EQUIPMENT UNDER TEST

3.1 Photo documentation of the EuT

Evolve G10:




FCC ID: DO4EVOLVE




FCC ID: DO4EVOLVE

Evolve G20:



FCC ID: DO4EVOLVE




FCC ID: DO4EVOLVE

Evolve P10:



FCC ID: DO4EVOLVE



FCC ID: DO4EVOLVE

Evolve P20:



FCC ID: DO4EVOLVE

GlobTek PSU, GT-2S5024D-R:



FCC ID: DO4EVOLVE


GlobTek PSU, GT-2S5024D-R-ES:




FCC ID: DO4EVOLVE

3.2 Ferrite Locations

Evolve G10




Evolve G20




FCC ID: DO4EVOLVE

Evolve P10



Evolve P20



FCC ID: DO4EVOLVE

**Ferrite Locations:**

1. Fair Rite P/N 734020 (Order No 2865-000-202) – Add two ferrites on the end of the Tx1 and Tx2 connection with one turn.
2. Fair Rite P/N 7248401 (CORE, FERRITE SUPPR W/CASE SFC-6) – Add one ferrite on the Tx1 and Tx2 cables with one turn.
3. Fair Rite P/N 284760 (Order No 0443806406) – Add a ferrite on the end of the DC Output cable of the GlobTek PSU with three turns through the ferrite.