



INTERTEK TESTING SERVICES

Internal photos

Corded Phone with 433MHz receiver assembly




Corded Phone Main PCB component side (View 1)




INTERTEK TESTING SERVICES

Internal photos

Corded Phone Main PCB component side (View 2)



Corded Phone Main PCB solder side



INTERTEK TESTING SERVICES

Internal photos

Corded Phone LCD Display front side (View 1)




Corded Phone LCD Display front side (View 2)




INTERTEK TESTING SERVICES

Internal photos

Corded Phone LCD Display rear side




Corded Phone Oscillator component side




INTERTEK TESTING SERVICES

Internal photos

Corded Phone Oscillator solder side




Corded Phone Keypad front side




INTERTEK TESTING SERVICES

Internal photos

Corded Phone Keypad rear side (View 1)




Corded Phone Keypad rear side (View 2)



INTERTEK TESTING SERVICES

Internal photos

Corded Phone's Headset Volume Control component side




Corded Phone's Headset Volume Control solder side




INTERTEK TESTING SERVICES

Internal photos

Corded Phone Hook Switch component side




Corded Phone Hook Switch solder side



INTERTEK TESTING SERVICES

Internal photos

433MHz Receiver component side



433MHz Receiver solder side

