



Logitech

March 5, 2008

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, Maryland 21046

Subject: FCC ID: DZLA-00006 Attestation Letter for Modifications

To Whom It May Concern,

During the EMI testing of the subject device, the following modifications were required for compliance:

C36 & C37 removed

C39 = 9pF capacitor installed between C36 pin 1 and C37 pin 1 landing pad.

These modifications will be implemented in all production units of the subject device. Alternately, different modifications may be used if they are tested and verified to produce the same or lower level of emissions.

If further clarification of Logitech's wireless headset is needed, please feel free to contact me at (360) 256-3216, via e-mail at aaron_cohen@logitech.com, or fax (360) 896-2020.

Sincerely,

Aaron Cohen

Aaron Cohen
Compliance Engineer
Logitech, Inc.