



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

September 10, 2002

RE: Behavior Tech Computer Corporation

FCC ID: E5XKB8188RF

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) The labeling should contain the proper FCC statements (15.19). The label supplied only shows the Canadian Labeling requirements. Please provide an updated label.
- 2) FYI, The users manual does not appear to contain all the proper information for the DoC portion of the system (Receiver).

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.