






UMTS/CDMA radio
located below this shield

System Board with 2nd shield





MAIN ▲
T77Z204.10 HF
REV: 04L4
MEID A1000004BC4C19
IMEI 357485040006373
Made in China 1101145

F138019I
T77Z204T10 HF
41014701-04L4
QC PN: 20-VM173-P3

SDX A4 ICT 142
145-462-007
COPYRIGHT 2009 INTERMEC
Assembled in Singapore
Made in Taiwan

VCL Ref: CC-40620701
VCL SIN111000709

TOPSEARCH
SR17428/10 42:0
94V-0 TS-M-8V01C C
C133 C134 C136 C137 C138 C139 C140 C141
MADE IN CHINA
ASSEMBLED IN SINGAPORE


RESET SW2
SW1
C15 C123
C16 C124
C17 C125
C18 C126
C19 C129
C20 C130
C131 C132
145-411-001
COPYRIGHT
2009 INTERMEC


224-869-0401
CHINA 94V-0
TS-M-8V01C C
SR17428/10 T22
C110 T23
J2
C47
VCL Ref: CA-48690401
VCL SIN104800116
6

WLAN/BLUETOOTH
RADIO




Back of System Board with and without shield





Bluetooth Radio module
without shield



Bluetooth Radio module
with shield

UMTS/CDMA Radio Module

Figure 1 Module Top View Internal Photograph (Shield Removed)




Figure 2 Module Bottom View External Photograph (Label Removed)

