


EMC Technologies Report Number: M050422_Cert_WLL4070_11abg_NII_BT

APPENDIX K
Harmonics - WLL4070 802.11a (NII)




Harmonics – Channel 36

Date: 15.APR.2005 09:31:33



Harmonics - Channel 42

Ref Lvl	Marker 1 [T1]	RBW	1 MHz	RF Att	30 dB
15 dBm	1.39 dBm	VBW	1 MHz		
	5.22044088 GHz	SWT	600 ms	Unit	dBm




Date: 15.APR.2005 09:43:39



Harmonics - Channel 50

Marker 1 [T1]	RBW	1 MHz	RF Att	30 dB
Ref Lvl	2.21 dBm	VBW	1 MHz	
15 dBm	5.22044088 GHz	SWT	600 ms	Unit dBm




Date: 15.APR.2005 09:41:12



Harmonics - Channel 52

Marker 1 [T1] RBW 1 MHz RF Att 30 dB
Ref Lvl 9.25 dBm VBW 1 MHz
15 dBm 5.22044088 GHz SWT 600 ms Unit dBm




Date: 15.APR.2005 09:34:10



Harmonics - Channel 58

Marker 1 [T1] RBW 1 MHz RF Att 30 dB
Ref Lvl 6.44 dBm VBW 1 MHz
15 dBm 5.29859719 GHz SWT 600 ms Unit dBm




Date: 15.APR.2005 09:39:01



Harmonics - Channel 64

Marker 1 [T1] RBW 1 MHz RF Att 30 dB
Ref Lvl 9.64 dBm VBW 1 MHz
15 dBm 5.29859719 GHz SWT 600 ms Unit dBm



Date: 15.APR.2005 09:36:40

