


EMC Technologies Report Number: M050510_Cert_WLL4070_11abg_NII_BT


APPENDIX K
Harmonics - WLL4070 802.11a (NII)



Harmonics – Channel 36


Date: 19.MAY.2005 09:24:26



Harmonics - Channel 52


Date: 19.MAY.2005 09:27:00



Harmonics - Channel 64

Date: 19.MAY.2005 09:29:09




Harmonics - Channel 42 (Turbo)

Date: 19.MAY.2005 09:54:29



Harmonics - Channel 50 (Turbo)

Marker 1 [T1] RBW 300 kHz RF Att 30 dB
Ref Lvl -0.09 dBm VBW 1 MHz
15 dBm 5.22044088 GHz SWT 1.1 s Unit dBm




Date: 19.MAY.2005 09:52:29



Harmonics - Channel 58 (Turbo)

Ref Lvl	Marker 1 [T1]	RBW	300 kHz	RF Att	30 dB
15 dBm	3.98 dBm	VBW	1 MHz		
	5.22044088 GHz	SWT	1.1 s	Unit	dBm



Date: 19.MAY.2005 09:40:50

