


EMC Technologies Report Number: M050750_Cert_WLL4070_NII_BT

APPENDIX K
Harmonics - WLL4070 802.11a (NII)



Harmonics – Channel 36




Date: 17.AUG.2005 08:28:12



Harmonics - Channel 52


Marker 1 [T1] RBW 300 kHz RF Att 30 dB
Ref Lvl 6.09 dBm VBW 1 MHz
15 dBm 5.22044088 GHz SWT 1.1 s Unit dBm



Date: 17.AUG.2005 08:38:24




Harmonics - Channel 64



Date: 17.AUG.2005 08:43:56




Harmonics - Channel 42 (Turbo)

Date: 17.AUG.2005 08:31:23

Harmonics - Channel 50 (Turbo)


Marker 1 [T1] RBW 300 kHz RF Att 30 dB
Ref Lvl 1.41 dBm VBW 1 MHz
15 dBm 5.22044088 GHz SWT 1.1 s Unit dBm



Date: 17.AUG.2005 08:34:52

Harmonics - Channel 58 (Turbo)

Marker 1 [T1] RBW 300 kHz RF Att 30 dB
Ref Lvl 5.85 dBm VBW 1 MHz
15 dBm 5.22044088 GHz SWT 1.1 s Unit dBm



Date: 17.AUG.2005 08:49:39