



Report No.: HK08011045-2
Bluetooth Mode
AC Mains

Report No.:HK08011045-2

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement: x QP / + AV


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

2	1	9k	30M	EW0699
12	9k	30M	EW0090	





Report No.: HK08011045-2
Bluetooth Mode
AC Mains

Report No.:HK08011045-2

Scan Settings (1 Range)

----- Frequencies -----				----- Receiver Settings -----				
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results