



2111 North Molter Road  
Liberty Lake, Washington 99019  
509.924.9900 Tel  
509.891.3355 Fax  
800.635.5461  
[www.itron.com](http://www.itron.com)

06 January, 2011

Subject: Cover letter SAR  
FCC: EO9FC300SR; IC:864D-FC300SR

Dear Sir/Madam:

This letter is to explain that the maximum power out for the 902-928 MHz radio has been set to a lower level and was done after the SAR testing and report were done. There were no hardware changes in setting the new lower power out. The SAR report is still valid to show compliance.

Sincerely,

A handwritten signature in black ink that reads "Jay R. Holcomb". The signature is fluid and cursive, with "Jay R." on top and "Holcomb" on the line below.

Jay R. Holcomb  
R&D Program and Regulatory Manager  
[jay.holcomb@itron.com](mailto:jay.holcomb@itron.com)  
Itron, Inc.

Enclosure: n/a  
cc: n/a