



49. SOLDER SIDE OF GLIDE PAD



54. COMPONENT SIDE OF PORT BAR (Mode 5)




GESTEK Lab.

FCC ID: EUNDESIGNOTE56

Report #: 98A037F

N0 3, Pau-Tou-Tsuo Valley, Chia-Pau Tsuen, Lin Kou Hsiang, Taipei County, Taiwan, R.O.C. Tel:886-2-2603-5321 Fax:886-2-2603-5325

55. SOLDER SIDE OF PORT BAR (Mode 5)



GESTEK Lab.

FCC ID: EUNDESIGNOTE56


Report #: 98A037F

N0 3, Pau-Tou-Tsuo Valley, Chia-Pau Tsuen, Lin Kou Hsiang, Taipei County, Taiwan, R.O.C. Tel:886-2-2603-5321 Fax:886-2-2603-5325

60. COMPONENT SIDE OF ADAPTOR





61. SOLDER SIDE OF ADAPTOR




52. INNER VIEW OF PORT BAR (Mode 5)

53. INNER VIEW OF PORT BAR (Mode 5)





32. INVERTOR BOARD (Mode 3)



58. INNER VIEW OF ADAPTOR

59. INNER VIEW OF ADAPTOR



36. PANEL OF NOTEBOOK (Mode 4)

37. PANEL OF NOTEBOOK (Mode 4)

