

Out of Band - 5.735 GHz

9090301B
4-22-98
OUT OF BAND
LOW BAND


ATTEN 10dB

MKR --71.33dBm

RL 0dBm

10dB/

28.675GHz



START 26.500GHz

STOP 31.000GHz

*RBW 100kHz

VBW 100kHz

SWP 1.20sec

Out of Band - 5.735 GHz

5090301 B
4-22-98
OUT OF BAND
LOW BAND


ATTEN 10dB

MKR -64.83dBm

RL 0dBm

10dB/

36.850GHz



START 31.000GHz

STOP 40.000GHz

*RBW 100kHz

VBW 100kHz

SWP 2.30sec

Out of Band - 5.77 GHz

3010301B
9-22-10
OUT OF BAND
MID BAND


ATTEN 10dB

MKR -71.00dBm

RL 0dBm

10dB/

30.888GHz



START 26.500GHz

STOP 31.000GHz

*RBW 100kHz

VBW 100kHz

SWP 1.20sec

Out of Band - 5.77 GHz

8090301B
9-27-98
OUT OF BAND
MID BAND


ATTEN 10dB

MKR -64.00dBm

RL 0dBm

10dB/

38.590GHz



START 31.000GHz

STOP 40.000GHz

*RBW 100kHz

VBW 100kHz

SWP 2.30sec

0090301 L3
9-22-01
OUT OF BAND
1768 BAND

Out of Band - 5.80 GHz


ATTEN 10dB

MKR -72.00dBm

RL 0dBm

10dB/

29.733GHz



START 26.500GHz

STOP 31.000GHz

*RBW 100kHz

VBW 100kHz

SWP 1.20sec


00403012
9-22-90
OUT OF BAND
HIGH BAND

Out of Band - 5.80 GHz

ATTEN 10dB
RL 0dBm

10dB/

MKR -64.83dBm
37.930GHz



START 31.000GHz STOP 40.000GHz
*RBW 100kHz VBW 100kHz SWP 2.30sec