

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701


PMN: VM929HQ PU, VM929-2HQ PU

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701


PMN: VM929HQ PU, VM929-2HQ PU

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701


PMN: VM929HQ PU, VM929-2HQ PU

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01  
IC: 1135B-80346701  
PMN: VM929HQ PU, VM929-2HQ PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701


PMN: VM929HQ PU, VM929-2HQ PU

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU

---

## INTERTEK TESTING SERVICES

---

### Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: VM929HQ PU, VM929-2HQ PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: 928 Plus PU, 928 Plus Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: 928 Plus PU, 928 Plus Twin PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: 928 Plus PU, 928 Plus Twin PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701


PMN: 928 Plus PU, 928 Plus Twin PU

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701


PMN: 928 Plus PU, 928 Plus Twin PU

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: 928 Plus PU, 928 Plus Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701


PMN: 928 Plus PU, 928 Plus Twin PU

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701


PMN: 928 Plus PU, 928 Plus Twin PU

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701


PMN: 928 Plus PU, 928 Plus Twin PU

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: 928 Plus PU, 928 Plus Twin PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: 928 Plus PU, 928 Plus Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701


PMN: 928 Plus PU, 928 Plus Twin PU

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: 928 Plus PU, 928 Plus Twin PU



---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: 928 Plus PU, 928 Plus Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: 928 Plus PU, 928 Plus Twin PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: 928 Plus PU, 928 Plus Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: 928 Plus PU, 928 Plus Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: 928 Plus PU, 928 Plus Twin PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701


PMN: 928 Plus PU, 928 Plus Twin PU

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: 928 Plus PU, 928 Plus Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: 928 Plus PU, 928 Plus Twin PU

---

## INTERTEK TESTING SERVICES

---

### Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: 928 Plus PU, 928 Plus Twin PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU


---

## INTERTEK TESTING SERVICES

---

### Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701


PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701


PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701


PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU


---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU

---

# INTERTEK TESTING SERVICES

---

## Equipment Photographs

(Internal)



---

FCC ID: EW780-3467-01

IC: 1135B-80346701

PMN: Advanced HQ Max PU, Advanced HQ Max Twin PU