



Report No.: HK08011434-1
Model: DS6111
Talk Mode
AC Mains "L"

Report No.: HK08011434-1

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement: x QP / + AV

Meas Time: 1 s


Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

2 1 9k 30M EW0699

12 9k 30M EW1449



Ctrl No.: N/A



Report No.: HK08011434-1
Model: DS6111
Talk Mode
AC Mains "L"

Report No.:HK08011434-1

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results



Report No.: HK08011434-1
Model: DS6121
Talk Mode
AC Mains "L"

Report No.:HK08011434-1

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB


Final Measurement: x QP / + AV

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
2	1 9k	30M	EW0699
12	9k	30M	EW1449



Ctrl No.:



Report No.: HK08011434-1
Model: DS6121
Talk Mode
AC Mains "L"

Report No.:HK08011434-1

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
150k	30M	5k	10k	PK+AV	10ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl No.: