

February 9, 2000

Federal Communications Commission
Application Processing Branch
7435 Oakland Mills Road
Columbia, MD 21046

Ref: Maxon America, Inc., FCC ID: F3JSM-6450U6; EA96718

Errors have been noted on the Form 731 of the referenced application. Please make corrections as noted below:

1. Please amend FCC ID to read FCC ID: F3JSM6450U6, there should be no dash between the M and 6, as shown on the ID label diagram.
2. Please amend Form 731, item 10:

Equipment will be operated under FCC Rule Part(s): 22, 74, 90 and 95.

Sincerely,
Hyak Laboratories, Inc.

Georgia Hall