

The Rated RF power output in watts for this equipment should be .42 rather than 12.5.