



Federal Communications Commission
Equipment Authorization Branch
7435 Oakland Mills Road
Columbia, MD 21046

8/16/2010

To Whom It May Concern:

In regards to RF Module, model VL4B, Fleetwood Group, Inc recognizes the required change of increasing the antenna feed resistor from 150 ohm to 180 ohm to achieve compliance, and will ensure the change is in place.

Thank you,

Will Buehler
Chief Technology Officer

Fleetwood Group, Inc.



Mail: P.O. Box 1259 Holland, MI 49422-1259 - Ship: 11832 James Street Holland, MI 49424
Phone: (616) 369-1142 - Toll Free (800) 257-6390 - Corporate Fax: (616) 820-8300

