

Internal photographs Transmitter PCB Primary Side shielding removed



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Transcore  
HVIN: E6V2 PMN: E5, E6  
Test: 221228  
Test to: 47CFR Parts 2, 90 and RSS-137  
File: E6V2 IntPho

SN: 22176999  
FCC ID: FIHE6PT90V2  
IC: 1584A-E6RSS137V2  
Date: January 23, 2023  
Page 1 of 7

Transmitter PCB Secondary Side




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Transcore  
HVIN: E6V2 PMN: E5, E6  
Test: 221228  
Test to: 47CFR Parts 2, 90 and RSS-137  
File: E6V2 IntPho

SN: 22176999  
FCC ID: FIHE6PT90V2  
IC: 1584A-E6RSS137V2  
Date: January 23, 2023  
Page 2 of 7

Inside enclosure




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Transcore  
HVIN: E6V2 PMN: E5, E6  
Test: 221228  
Test to: 47CFR Parts 2, 90 and RSS-137  
File: E6V2 IntPho

SN: 22176999  
FCC ID: FIHE6PT90V2  
IC: 1584A-E6RSS137V2  
Date: January 23, 2023  
Page 3 of 7


## Power Supply



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Transcore  
HVIN: E6V2 PMN: E5, E6  
Test: 221228  
Test to: 47CFR Parts 2, 90 and RSS-137  
File: E6V2 IntPho

SN: 22176999  
FCC ID: FIHE6PT90V2  
IC: 1584A-E6RSS137V2  
Date: January 23, 2023  
Page 4 of 7




Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Transcore  
HVIN: E6V2 PMN: E5, E6  
Test: 221228  
Test to: 47CFR Parts 2, 90 and RSS-137  
File: E6V2 IntPho

SN: 22176999  
FCC ID: FIHE6PT90V2  
IC: 1584A-E6RSS137V2  
Date: January 23, 2023  
Page 5 of 7


## Processing Board



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Transcore  
HVIN: E6V2 PMN: E5, E6  
Test: 221228  
Test to: 47CFR Parts 2, 90 and RSS-137  
File: E6V2 IntPho

SN: 22176999  
FCC ID: FIHE6PT90V2  
IC: 1584A-E6RSS137V2  
Date: January 23, 2023  
Page 6 of 7



Rogers Labs, Inc.  
4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Transcore  
HVIN: E6V2 PMN: E5, E6  
Test: 221228  
Test to: 47CFR Parts 2, 90 and RSS-137  
File: E6V2 IntPho

SN: 22176999  
FCC ID: FIHE6PT90V2  
IC: 1584A-E6RSS137V2  
Date: January 23, 2023  
Page 7 of 7