

Telemetry Receiver **SRX600**

Labeling Information

Document Reference Number: 10249

Lotek Wireless
115 Pony Drive
Newmarket, Ontario
Canada, L3Y 7B5

Tel: 905-836-6680
Fax: 905-836-6455
Web-site: www.lotek.com

The back of the SRX 600 Telemetry Receiver is shown, featuring several ports and labels. On the left, there is a USB port labeled "USB", a power input labeled "POWER" with "11-16V" and "400mA" specifications, and a "GPS Ant." port. Below the USB port is a "UUC POWER" port. In the center, a label reads "FCC ID: FW9SRX600", "MODEL: SRX 600", and "TELEMETRY RECEIVER". Below this label, it states "THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING CONDITIONS:" followed by two conditions: "(1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE AND (2) THIS DEVICE MUST ACCEPT INTERFERENCE THAT MAY CAUSE UNDESIRED OPERATION." A warning note below the conditions reads: "WARNING: MODIFICATION OF THIS DEVICE TO RECEIVE CELLULAR RADIOTELEPHONE SERVICE SIGNALS IS PROHIBITED UNDER FCC RULES AND FEDERAL LAW." On the right, there is a "FRONT CHG" port labeled "18V" and "1000mA". At the bottom, there are three ports labeled "ASP_8", "SERIAL II", and "SERIAL I/Modem". The serial ports are D-sub connectors. The "ASP_8" port is an 8-pin connector. The "SERIAL II" and "SERIAL I/Modem" ports are 9-pin connectors. The device is secured with screws around the perimeter.

POWER 11-16V 400mA

GPS Ant.

USB

UUC POWER

S/N: 6107

FCC ID: FW9SRX600
MODEL: SRX 600
TELEMETRY RECEIVER

THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES.
OPERATION IS SUBJECT TO THE FOLLOWING CONDITIONS:
(1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE AND
(2) THIS DEVICE MUST ACCEPT INTERFERENCE THAT MAY CAUSE
UNDESIRED OPERATION.

WARNING: MODIFICATION OF THIS DEVICE TO RECEIVE CELLULAR RADIOTELEPHONE
SERVICE SIGNALS IS PROHIBITED UNDER FCC RULES AND FEDERAL LAW.

FRONT CHG
18V 1000mA

ASP_8 SERIAL II SERIAL I/Modem