






Plot on Channel 6925 MHz



Plot on Channel 7005 MHz



Plot on Channel 7085 MHz







EUT Mode

802.11be EHT80 FullRU


Plot on Channel 5985 MHz




Plot on Channel 6225 MHz



Plot on Channel 6385 MHz




Plot on Channel 6465 MHz







Plot on Channel 6545 MHz




Plot on Channel 6625 MHz




Plot on Channel 6705 MHz




Plot on Channel 6785 MHz



Plot on Channel 6865 MHz




Plot on Channel 6945 MHz





Plot on Channel 7025 MHz







EUT Mode

802.11be EHT160 FullIRU


Plot on Channel 6025 MHz




Plot on Channel 6185 MHz



Plot on Channel 6345 MHz




Plot on Channel 6505 MHz







Plot on Channel 6665 MHz



Plot on Channel 6825 MHz



Plot on Channel 6985 MHz






EUT Mode


802.11be EHT320 FullIRU

Plot on Channel 6105 MHz




11:23:18 AM 01/04/2025

Plot on Channel 6265 MHz




11:23:14 AM 01/04/2025

Plot on Channel 6425 MHz



12:50:19 PM 01/04/2025


Plot on Channel 6585 MHz




01:00:19 PM 01/04/2025



Plot on Channel 6745 MHz



Plot on Channel 6905 MHz






MIMO <Ant. 4+3+2+1(2)>

EUT Mode


802.11be EHT20 FullRU

Plot on Channel 5955 MHz

Plot on Channel 6195 MHz




01:31:28 PM 01/02/2025




02:00:31 PM 01/02/2025

Plot on Channel 6415 MHz

Plot on Channel 6435 MHz




02:13:10 PM 01/02/2025




02:23:11 PM 01/02/2025




Plot on Channel 6475 MHz




Plot on Channel 6515 MHz




Plot on Channel 6535 MHz




Plot on Channel 6695 MHz



Plot on Channel 6855 MHz




Plot on Channel 6875 MHz







Plot on Channel 6895 MHz




Plot on Channel 6995 MHz



Plot on Channel 7095 MHz



Plot on Channel 7115 MHz






EUT Mode


802.11be EHT40 FullRU

Plot on Channel 5965 MHz




05:07:25 PM 01/02/2025

Plot on Channel 6205 MHz




05:15:14 PM 01/02/2025

Plot on Channel 6405 MHz



05:29:09 PM 01/02/2025


Plot on Channel 6445 MHz



06:10:33 PM 01/02/2025




Plot on Channel 6485 MHz




06:19:35 PM 01/02/2025

Plot on Channel 6525 MHz




06:36:06 PM 01/02/2025

Plot on Channel 6565 MHz




06:42:58 PM 01/02/2025

Plot on Channel 6685 MHz




06:49:45 PM 01/02/2025

Plot on Channel 6845 MHz



07:00:41 PM 01/02/2025


Plot on Channel 6885 MHz




07:15:37 PM 01/02/2025




Plot on Channel 6925 MHz



Plot on Channel 7005 MHz



Plot on Channel 7085 MHz







EUT Mode

802.11be EHT80 FullRU


Plot on Channel 5985 MHz



Plot on Channel 6225 MHz



Plot on Channel 6385 MHz



Plot on Channel 6465 MHz

