



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

August 29, 2003

RE: FCC ID: GMLRH-25
Attention: nerina.walton@nokia.com

I have a few comments on this Application.

1. Please provide an actual FCC ID label with the FCC ID number on it for this device. The label location exhibit you provided does not indicate the actual FCC ID number of the device. -
2. Please note that OET65C and IEEE1528 recommend a maximum of 5% power drift. If greater drift is experienced a detailed explanation needs to be given. Please note that on the plot on page 41 of the SAR report you show a power drift in excess of 10%. Please explain. -
3. Please note that while the power measurements between the EMC and SAR report are within the recommended 5%, the SAR power values are not the higher values. Please note that SAR power is to be the higher power reported if there is a difference. Please provide a SAR report with the higher power being reported. Alternately please explain if the difference is an error in rounding off the decimal places. -

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.