

April 15, 2004

TRW Automotive Electronics
24175 Research Drive
Farmington Hills, MI 48335
Tel: 248.478.7210
Fax: 248.478.7241

RE: Certification for TRW TPM '05 Receiver
TRW Model #: 211646
FCC ID: GQ4-32R
Canada IC: 1470A-4R

FCC/IC IDENTIFIER AND MODEL NUMBER

Please see Figure 1 for the FCC/IC identifier location and Figure 2 for the model number location.




Figure 1. FCC/IC Identifier Model Number Location

The Honda model number for the receiver is:39350-SHJ-A6
39350-SJA-A0
39350-SJC-A0
39350-S9V-A0

The FCC ID for the receiver is:GQ4-32R

The Canada IC number for the receiver is:1470A-4R