

Honeywell International Inc

July 19, 2024

Attestation

We, Honeywell International Inc, attest the followings for our device FCC ID: HD5-CT37X0N.

- a. The equipment only punctures to optimize network performance and never to avoid licensed Incumbents.
- b. If a licensed incumbent is detected, the equipment will either use bandwidth reduction or a complete move of the channel for avoidance.
- c. If a channel is punctured in order to optimize network performance, it will continue to use CBP in the punctured region.



Cindy Jiang
Cindy.Jiang@honeywell.com