

FCC ID: HEDEAP2316A

Issued on Aug. 9, 2005 Report No.: FR570703

5.5.8. Photographs of Conducted Emission Test Configuration



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 36 of 62 Issued Date : Aug. 9, 2005



FCC ID: HEDEAP2316A

Issued on Aug. 9, 2005

5.6.12. Photographs of Radiated Emission Test Configuration



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 55 of 62

Report No.: FR570703

Issued Date : Aug. 9, 2005