

Lucy Tsai

From: ATL-Joyce [joyce@atl-lab.com.tw]
Sent: Wednesday, March 10, 2010 2:18 AM
To: Lucy Tsai
Cc: miller@atl-lab.com.tw; murphy@atl-lab.com.tw; linda@atl-lab.com.tw; queeni@atl-lab.com.tw
Subject: FW : Acer Incorporated, FCC ID: HLZ-AR5B95, Assessment NO.: AN10T0161, Notice#1
Attachments: Reply File_100310.rar

Dear Lucy~

Our reply listed below.

Q#1: As indicated in the Permissive change letter, a new antenna is added in this application. Please provide the antenna specification.

--> Attach antenna specification and confidentiality letter. The antenna specification need confidentiality(Permanent request).

Q#3: There has a WWAN (FCC ID: QISEM770W) installed in this laptop but there are not information address this WWAN module in this application. Where is the antenna located of WWAN? Can the WWAN co-locate with the WLAN module? Please address.

--> 1. The WWAN antenna information, please see the page 19 in report.

2. WWAN and WWAN-WLAN co-location issue will be filed for C2PC by the WWAN module manufacturer.

Q#3: The frequency 18000MHz indicated in page 20 is duplicated. Please correct.

--> We've revised it(page 20).

Q#4: Please provide RF module's OEM installation guide.

--> Attach RF module's OEM installation guide file.

Best regards,

廖秋吟 Joyce Liao
Measurement Center

 **A Test Lab Techno Corp.**
晶復科技股份有限公司

TEL : +886-3-2710188 ext: 200

Mobile : +886-935176076

Address :桃園縣八德市長安街 140-1 號

E-mail : joyce@atl-lab.com.tw

Website : <http://www.atl-lab.com.tw>