



Acer Incorporated

8F, 88, Sec. 1, Hsin Tai Wu Rd., Hsichih

Taipei Hsien 221, Taiwan, R.O.C.

Tel : 886-2-2696-1234

Fax : 886-2-2696-3535

www.acer.com

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Attention: Application Examiner/ Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: HLZDMS100FBT

To The Commission:

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by Acer Incorporated will establish a new FCC ID under Acer Incorporated grantees code for purpose of marketing. The original grant to FCC ID: HLZDMS100FBT will remain in effect.

Per 2.933(b)

The original identification is FCC ID : TB6-BT809X

1. The original grant date is 07/14/2008.
2. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
3. The original test results are applicable and representative of this changed device.
4. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely,

Name: Harriot Lee
Title: Sr. Project Engineer
Date: 2010/6/22