

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/ RSS 247 Class II Permissive Change
HSW-CCT24
4492A-CCT24
17-0439
April 9, 2018
Murata Electronics North America
CCT24

Internal Photographs




Figure 1. Top of Module with Shield Removed

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15/ RSS 247 Class II Permissive Change
HSW-CCT24
4492A-CCT24
17-0439
April 9, 2018
Murata Electronics North America
CCT24




Figure 2. Bottom of Module with Shield removed

Note: Circuit identified above was originally on top of the board and has been moved to the bottom as shown above.