

Helen Zhao

Subject: FW: Fellowes, Inc., FCC ID: IDHBTHS03, Assessment NO.: AN04T4327, Notice#1



Revised Label.pdf Setup photos.doc Test report_01.pdf Test report_02.pdf

-----Original Message-----

From: hsieh
Sent: Wednesday, November 17, 2004 8:12 PM
To: Helen Zhao
Subject: Re: Fellowes, Inc., FCC ID: IDHBTHS03, Assessment NO.: AN04T4327, Notice#1

Hi Helen,

Attached please find the new FCC ID Label format, new test report and setup photos.

Re-Q#1: Please see the new label.

Re-Q#2: The sentence is not fit at that page. Please review the new test report 01.

Re-Q#3: Please see the new test report 02 for new Channel Separation test.

Re-Q#4: Please see the new setup photos.

Re-Q#5: Please see page 11 of the revise user manual. There is some important note sentences for RF exposure.

If it's not appropriate, please kindly contact me.

Thanks for your remind.

Best regards,

Joe Hsieh
ETC, Taiwan

-----Original Message-----

From: Compliance Certification Services [mailto:hzhao@ccsemc.com]
Sent: Tuesday, November 09, 2004 3:42 PM
To: Helen Zhao
Subject: Fellowes, Inc., FCC ID: IDHBTHS03, Assessment NO.: AN04T4327, Notice#1

Question #1: FCC ID label format shows "FCC ID: HBTHS03", which does not agree with form 731. Please correct.

Question #2: Test report section 4.4.2 Other emission indicates "Item of margin shown in above table refer to average limit." Based upon FCC15.209(d)

the emission limits for 30MHz - 1GHz are based on measurements employing a CISPR quasi-peak detector. Please explain.

Question #3: Section 11.4 Channel Separation of the test report shows the RBW was set far below 1% of the span during the test. Please redo the test by using the correct settings.

Question #4: There are three identical radiated emission test setup photos in the Setup Photos exhibit. Please provide one more photo to show the front view.

Question #5: The user manual does not include RF exposure statement: The antennas used for this transmitter must not be co-located or operating in conjunction with any other antenna or transmitter.

Best regards,
Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.