

Scott McCutchan

To: joey@celectronics.com; Ruby Hall
Subject: FCC ID: IE3VP43XX03

Mr. Madlangbayan,

In order for processing of this application (FCC ID: IE3VP43XX03) to continue, the following issue will have to be addressed:

1) The FCC ID can not be placed on the battery compartment cover. Please submit a new drawing showing where the FCC ID will be placed on the device.

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Please upload responses and/or exhibits to the electronic filing website.

Your correspondence number is IE3VP43XX03-1.

If you have any questions, feel free to contact me.

Best regards,

Scott McCutchan
Operations Manager
Compatible Electronics TCB
(714) 579-1489
fax (714) 579-1850
<http://www.celectronics.com>

Correspondence by Project

Project Number:

1056063835

Correspondence Number	Memo
IE3VP43XX03-1	Mr. McCutchan, I am attaching a new FCC ID revised location drawing. Please review it and reply if any questions may occur. Thank You Mr. Madlangbayan