

1 PRODUCT LABELING

1.1 FCC ID Label

This is the copy of the label stuck on the product (size is 35 mm x 64 mm)

For NCX400 :



NCX400

FCC ID: IGTNCX

Ethernet : 0.208.98.0.0.0

S/N :010600000065

For NCX200 :



NCX200

FCC ID: IGTNCX

Ethernet : 0.208.98.0.0.0

S/N :010400000072



This device complies with part 15 of the FCC Rules.
 Operation is subject to the following two conditions: (1)
 This device may not cause harmful interference, and (2)
 this device must accept any interference received,
 including interference that may cause undesired operation.

This device complies with part 15 of the FCC Rules.
 Operation is subject to the following two conditions: (1)
 This device may not cause harmful interference, and (2)
 this device must accept any interference received,
 including interference that may cause undesired operation.



MADE IN FRANCE



MADE IN FRANCE

For NCX040 :

**NCX040****FCC ID: IGTNCX****Ethernet : 0.208.98.0.0.0****S/N :011400000999**

For NCX220 :

**NCX220****FCC ID: IGTNCX****Ethernet : 0.208.98.0.0.0****S/N :011900000048**

This device complies with part 15 of the FCC Rules.
Operation is subject to the following two conditions: (1)
This device may not cause harmful interference, and (2)
this device must accept any interference received,
including interference that may cause undesired operation.

This device complies with part 15 of the FCC Rules.
Operation is subject to the following two conditions: (1)
This device may not cause harmful interference, and (2)
this device must accept any interference received,
including interference that may cause undesired operation.

**MADE IN FRANCE****MADE IN FRANCE**

1.2 Location of label on EUT

Label is stuck on the bottom face of the product (see picture).

