



EMC TEST SETUP PHOTOS




EMC Report #21624-1 AC Line - Part 15



EMC Report #21624-1 Part 15, PC Peripheral



EMC Report #21624-1 Antenna - Substitution



EMC Report #21624-1 Tx Radiated