



**MOTOROLA**

**Date:** October 21, 2008

**Subject:** Request for additional information regarding FCC ID: IHDP56JC1

**Reference:**

Correspondence Reference Number: IHD80995  
Confirmation Number: 8010170995-7  
Date of Original Email: October 20, 2008

**Prepared by:**

Andrew Bachler, Principal Staff Engineer  
Motorola Mobile Device Business  
Libertyville, Illinois 60048

Questions and responses follow:

1. Please submit an Operational Description of the BT transmitter.

**Response:** [Please refer to the BT Operational Description attached.](#)

2. The Cover Letter lists an incorrect FCC ID in the first paragraph. Please revise and resubmit.

**Response:** [Please refer to the revised cover letter attached.](#)

3. The schematic diagrams show a WLAN transmitter. Please confirm that this is not implemented in the EUT.

**Response:** [It is confirmed that WLAN application on this device is not implemented.](#)