



MOTOROLA

Date: June 13, 2008

Subject: Request for additional information regarding FCC ID: IHDP56JG1

Reference:

Correspondence Reference Number: IHD80354
Confirmation Number: 804210354
Date of Original Email: June 12, 2008

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois 60048

Questions and responses follow:

1. Cover Letter (Exh 13) states the device is capable of 900 and 1800 MHz. Please update to address the US related information.

Response: [Please refer to the revised Exhibit 13 attached.](#)

2. External Photograph with FCC ID label has the incorrect FCC ID. Please amend.

Response: [Please refer to the revised Exhibit 3 attached.](#)

3. Please provide a clear photograph of the circuit board showing electrical tracing for the internal photographs in Exhibit 3.

Response: [Please refer to the revised Exhibit 9 attached.](#)

4. Exhibit 6, 21777-1, Page 3 states EDGE is available, however the application does not appear to indicate the device contains EDGE. Please clarify.

Response: [Please refer to the revised Exhibit 6 attached where a typo of EDGE is corrected.](#)

5. Please submit JBP portion of this application.

Response: [There is no Part 15B Computer Peripheral on this device.](#)