



MOTOROLA

Date: Oct 14, 2009

Subject: Request for additional information regarding FCC ID: IHDP56KC5

Reference:

Correspondence Reference Number: IHD91108
Confirmation Number: 909151108-10
Date of Original Email: Oct. 12, 2009

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois 60048

Questions and responses follow:

1. Please submit the response from the FCC to the SAR lab's KDB re Release 6 HSPA testing.

Response: [Please refer to FCC PBA response \(Tracking Number 801424\) attached.](#)

2. Please indicate if DTS (WLAN) conducted output power was measured with an average or a peak detector.

Response: [Please refer to Version 2 of the WLAN test report submitted online.](#)

3. Please provide plots demonstrating DTS (WLAN) bandedge compliance.

Response: [Please refer to Version 2 of the WLAN test report submitted online.](#)

4. Please provide a more exact description of the support equipment used for Part 15B testing (model number, etc.).

Response: [Please refer to Version 2 of PC Peripheral test report and additional Exhibit 7 photos submitted online.](#)

5. It can be seen from the test set-up photos (not very clearly) that the test set-up used for Part 15B testing (both radiated and AC Line Conducted) does not meet the requirements for the test set-up specified in ANSI C63.4 (placement of devices on test stand and spacing between them). Please retest using the correct test set-up and submit new data (including clearer test set-up photos).

Response: Please refer to Version 2 of PC Peripheral test report and additional Exhibit 7 photos submitted online.