


EMC TEST SETUP PHOTOS




Radiated Emissions – BT & WLAN - BJ




EMC Report #23881 AC Line - Part 15



EMC Report #23881 Part 15, PC Peripheral



Antenna - Substitution



Tx Radiated