Description of Permissive Change

This report is prepared for FCC class II permissive change. The differences compared with the original are changing HW version, SW version and modifying antenna.

HW change list as below.

- For Motorola Security function
- For improving CS Susceptibility
- ➤ For ESD solution with +/- 15KV
- For Antenna Matching change

SW version changed from: STARLING_G_05.01.02D to STARLING_G_05.13.00R_S

Reference no.: RF990421C04C