



MOTOROLA

Date: February 25, 2003

Subject: Request for additional information (FCC ID: IHDT56CL1 Class II Permissive Change)

Reference:

Application Received	2/7/2003
Correspondence Reference Number:	230220.IHD
Confirmation Number:	TC3033
Date of Original Email:	2/20/2003

Prepared by:

Steven Hauswirth
Motorola Personal Communications Sector Product Safety Laboratory
Harvard, Illinois

Andrew Bachler, Principal Staff Engineer
Motorola Personal Communications Sector
Libertyville, Illinois

Summary of request for additional information

- 1) The SAR plots submitted do not correspond to the SAR data provided. Please amend accordingly.

Response: A new SAR report is submitted with the proper plots.

- 2) Please confirm that the new C331 housing style contains no metallic components/paint.

Response: The composition of C331 housing style is identical to the C332 style in the original application. The housing is plastic (no metallic parts), and the inside of the front housing contains a metallic paint.