





*Figure 1. AC Line Conducted Emissions Measurement Setup*



*Figure 2. Computer Peripheral AC Line Conducted Emissions Measurement Setup*



*Figure 3. Computer Peripheral Part 15 Radiated Emissions Measurement Setup*



*Figure 4. Part 22/24 Radiated Emissions Measurement Setup*