



MOTOROLA

Date: January 25, 2007

Subject: Request for additional information regarding FCC ID: IHDT56GR1

Reference:

Correspondence Reference Number: IHD7010
Confirmation Number: 701030010-11
Date of Original Email: January 25, 2007

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois

1. Please verify that GPRS mode is not available to the EUT (it was not tested in this mode for body SAR).

Response: Confirmed - GPRS mode is not available to the EUT.

2. The SAR information on p.78 of the user's manual does not contain the U.S. information (Standard incorrect, limit incorrect, listed measured SAR values incorrect, etc.). Please modify.

Response: No need to modify. The SAR information is located on the second page of Exhibit 8, right after the cover page. Please note that I am not referring to the page numbers shown at the bottom of each User Manual page, but to the page of the pdf file.

3. The statements required by Sections 15.21 and 15.105 are not in the User's Manual. Please modify.

Response: No need to modify. The statements required by Sections 15.21 and 15.105 are located on the fourth page of Exhibit 8. Please note that I am not referring to the page numbers shown at the bottom of each User Manual page, but to the page of the pdf file.