



MOTOROLA

Date: June 02, 2008

Subject: Request for additional information regarding FCC ID: IHDT56JA1

Reference:

Correspondence Reference Number: IHD80458
Confirmation Number: 805190458
Date of Original Email: May 22, 2008

Prepared by:

Andrew Bachler, Principal Staff Engineer
Motorola Mobile Device Business
Libertyville, Illinois 60048

Questions and responses follow:

1. HAC T-coil Setup Photos appear to have been not tested “via conducted setup with CMU200” as described on Page 8, Exhibit 6B-2. Please clarify how this test was setup.

Response: [Please refer to the supplement response attached.](#)

2. Please provide EVDO-A RF conducted powers evaluated for both FETAP and RETAP mode per FCC SAR Measurement Procedures on Page 6. Only one was found.

Response: [Please refer to the supplement response attached.](#)

3. Exhibit 7D Page 3 indicates Slider configuration. Please clarify about this C2PC application.

Response: [Please refer to the revised the test setup photos attached.](#)