




EMC TEST SETUP PHOTOS




EMC Report #21531 AC Line - Part 15



EMC Report #21531 Part 15, PC Peripheral



EMC Report #21531 Antenna - Substitution



EMC Report #21531 Tx Radiated