



## EMC TEST SETUP PHOTOS



EMC Report #22718 AC Line - Part 15



EMC Report #22718 Part 15, PC Peripheral



EMC Report #22718 Antenna - Substitution



EMC Report #22718 Tx Radiated