

EMC TEST SETUP PHOTOS




Radiated Emissions – BT & WLAN




EMC Report #23695 AC Line - Part 15



EMC Report #23695 Part 15, PC Peripheral



EMC Report #23695 Antenna - Substitution



EMC Report #23695 Tx Radiated