DYNAMIC FREQUENCY SELECTION DFS Test Report

APPLICANT : Motorola Mobility, LLC EQUIPMENT : Mobile Cellular Phone

BRAND NAME : Motorola

MODEL NAME : 10061 (Single SIM), 10058 (Dual SIM)

FCC ID : IHDT56WA3

STANDARD : FCC Part 15 Subpart E

CLASSIFICATION: (NII) Unlicensed National Information Infrastructure

This is a variant report which is only valid together with the original test report. The product was received on Feb. 03, 2017. We, SPORTON INTERNATIONAL INC., would like to declare that the tested sample has been evaluated in accordance with the procedures and shown to be compliant with the applicable technical standards.

The test results in this report apply exclusively to the tested model / sample. Without written approval of SPORTON INTERNATIONAL INC., the test report shall not be reproduced except in full.

Reviewed by:

Jones Tsai / Manager





Report No.: FZ720310-04

SPORTON INTERNATIONAL INC.

No. 52, Hwa Ya 1st Rd., Hwa Ya Technology Park, Kwei-Shan District, Tao Yuan City, Taiwan, R.O.C.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WA3 Page Number : 1 of 4
Report Issued Date : Mar. 20, 2017
Report Version : Rev. 01

Report Template No.: BU5-FZ15EDFS Version 1.0

TABLE OF CONTENTS

RE	REVISION HISTORY3					
1	GENE	RAL DESCRIPTION	.4			
		Applicant				
	1.2	Manufacturer	.4			
	1.3	Feature of Equipment Under Test	. 4			
ΑP	PENDI	X A. ORIGINAL REPORT				

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WA3 Page Number : 2 of 4
Report Issued Date : Mar. 20, 2017
Report Version : Rev. 01

Report Template No.: BU5-FZ15EDFS Version 1.0

Report No. : FZ720310-04

REVISION HISTORY

REPORT NO.	VERSION	DESCRIPTION	ISSUED DATE
FZ720310-04	Rev. 01	Initial issue of report	Mar. 20, 2017

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WA3 Page Number : 3 of 4
Report Issued Date : Mar. 20, 2017
Report Version : Rev. 01

Report No. : FZ720310-04

Report Template No.: BU5-FZ15EDFS Version 1.0

General Description

1.1 Applicant

Motorola Mobility, LLC

222 W Merchandise Mart Plaza, Suite 1800, Chicago, IL 60654, United States

1.2 Manufacturer

Motorola Mobility, LLC

222 W Merchandise Mart Plaza, Suite 1800, Chicago, IL 60654, United States

1.3 Feature of Equipment Under Test

Product Feature					
Equipment	Mobile Cellular Phone				
Brand Name	Motorola				
Model Name	10061 (Single SIM), 10058 (Dual SIM)				
FCC ID	IHDT56WA3				
	GSM/EGPRS/WCDMA/HSPA/LTE/NFC/FM				
EUT supports Radios application	WLAN 11b/g/n HT20				
EO I Supports Radios application	WLAN 11a/n HT20/HT40				
	Bluetooth BR/EDR/LE				
HW Version	DVT2				
EUT Stage	Identical Prototype				

Remark: This is a variant report. All the test cases were performed on original report which can be referred to Sporton Report Number FZ720310.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 Report Issued Date: Mar. 20, 2017 FAX: 886-3-328-4978 Report Version : Rev. 01 FCC ID: IHDT56WA3

Report Template No.: BU5-FZ15EDFS Version 1.0

: 4 of 4

Page Number

Report No.: FZ720310-04

Appendix A. Original Report

Please refer to Sporton report number FZ720310.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WA3 Page Number : A1 of A1
Report Issued Date : Mar. 20, 2017
Report Version : Rev. 01

Report No. : FZ720310-04

Report Template No.: BU5-FZ15EDFS Version 1.0