# **FCC RF Test Report**

APPLICANT : Motorola Mobility, LLC EQUIPMENT : Mobile Cellular Phone

BRAND NAME : Motorola MODEL NAME : 10720

FCC ID : IHDT56WB2

STANDARD : FCC Part 15 Subpart C §15.247

**CLASSIFICATION**: (DSS) Spread Spectrum Transmitter

This is a variant report which is only valid together with the original test report. The product was received on Mar. 31, 2017 and testing was completed on Apr. 29, 2017. We, SPORTON INTERNATIONAL INC., would like to declare that the tested sample has been evaluated in accordance with the test procedures and has been in compliance with the applicable technical standards.

The test results in this report apply exclusively to the tested model / sample. Without written approval of SPORTON INTERNATIONAL INC., the test report shall not be reproduced except in full.

Reviewed by: Joseph Lin / Supervisor

Approved by: Jones Tsai / Manager



No. 52, Hwa Ya 1st Rd., Hwa Ya Technology Park, Kwei-Shan District, Tao Yuan City, Taiwan, R.O.C.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : 1 of 17
Report Issued Date : May 19, 2017

Report Version

1190

: Rev. 01

Report No.: FR733129-04A

# **TABLE OF CONTENTS**

		N HISTORY	
SU	MMAR	Y OF TEST RESULT	4
1	GENE	ERAL DESCRIPTION	5
	1.1	Applicant	5
	1.2	Manufacturer	5
	1.3	Product Feature of Equipment Under Test	5
	1.4	Product Specification of Equipment Under Test	6
	1.5	Modification of EUT	6
	1.6	Testing Location	7
	1.7	Applicable Standards	7
2	TEST	CONFIGURATION OF EQUIPMENT UNDER TEST	8
	2.1	Carrier Frequency Channel	8
	2.2	Descriptions of Test Mode	9
	2.3	Test Mode	9
	2.4	Connection Diagram of Test System	10
	2.5	Support Unit used in test configuration and system	10
	2.6	EUT Operation Test Setup	10
3	TEST	RESULT	11
	3.1	Radiated Band Edges and Spurious Emission Measurement	11
	3.2	Antenna Requirements	15
4	LIST	OF MEASURING EQUIPMENT	16
5	UNCE	ERTAINTY OF EVALUATION	17
API	PENDI	X A. RADIATED SPURIOUS EMISSION	
ΑP	PENDI	X B. RADIATED SPURIOUS EMISSION PLOTS	
ΑP	PENDI	X C. DUTY CYCLE PLOTS	
۸DI	DENIDI	Y D OPIGINAL PEROPT	

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : 2 of 17
Report Issued Date : May 19, 2017
Report Version : Rev. 01

Report No. : FR733129-04A

# **REVISION HISTORY**

REPORT NO.	VERSION	DESCRIPTION	ISSUED DATE
FR733129-04A	Rev. 01	Initial issue of report	May 19, 2017

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : 3 of 17
Report Issued Date : May 19, 2017
Report Version : Rev. 01

Report No. : FR733129-04A

# **SUMMARY OF TEST RESULT**

Report FCC Rule		Description	Limit	Result	Remark
		Radiated Band Edges			Under limit
3.1		and Radiated Spurious 15.209(a) & 15.247(d)		Pass	6.94 dB at
		Emission			31.350 MHz
3.2	15.203 & 15.247(b)	Antenna Requirement	N/A	Pass	-

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : 4 of 17
Report Issued Date : May 19, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1

# 1 General Description

### 1.1 Applicant

#### **Motorola Mobility, LLC**

222 W Merchandise Mart Plaza, Suite 1800, Chicago, IL 60654, United States

### 1.2 Manufacturer

#### Motorola Mobility, LLC

222 W Merchandise Mart Plaza, Suite 1800, Chicago, IL 60654, United States

# 1.3 Product Feature of Equipment Under Test

Product Feature				
Equipment	Mobile Cellular Phone			
Brand Name	Motorola			
Model Name	10720			
FCC ID	IHDT56WB2			
IMEI Code	990007530005609			
EUT supports Radios application	CDMA/EV-DO/GSM/EGPRS/WCDMA/HSPA/LTE/NFC WLAN 11b/g/n HT20 WLAN 11a/n HT20/HT40 WLAN 11ac VHT20/VHT40/VHT80 Bluetooth BR/EDR/LE			
HW Version	DVT2			
EUT Stage	Identical Prototype			

Report No.: FR733129-04A

#### Remark:

- 1. The above EUT's information was declared by manufacturer. Please refer to the specifications or user's manual for more detailed description.
- 2. This is a variant report. All the test cases were performed on original report which can be referred to Sporton Report Number FR733129A.

 SPORTON INTERNATIONAL INC.
 Page Number
 : 5 of 17

 TEL: 886-3-327-3456
 Report Issued Date
 : May 19, 2017

 FAX: 886-3-328-4978
 Report Version
 : Rev. 01

FCC ID : IHDT56WB2 Report Template No.: BU5-FR15CBT Version 1.1

Accessory List					
AC Adoptor 4	Brand Name: Motorola				
AC Adapter 1	Model Name: SPN5970A				
AC Adoptor 2	Brand Name: Motorola				
AC Adapter 2	Model Name: SPN5993A				
AC Adoptor 2	Brand Name: Motorola				
AC Adapter 3	Model Name: SPN5978A				
Pottory 1	Brand Name: Motorola				
Battery 1	Model Name: SNN5986A				
Battery 2	Brand Name: Motorola				
Battery 2	Model Name: SNN5897A				
Earphone	Brand Name: Motorola				
Earphone	Model Name: SH38C16618				
USB Cable	Brand Name: Motorola				
USB Cable	Model Name: SKN6473A				
USB-C Data Cable	Brand Name: Motorola				
USB-C Data Cable	Model Name: SKN6474A				

# 1.4 Product Specification of Equipment Under Test

Standards-related Product Specification			
Tx/Rx Frequency Range	2402 MHz ~ 2480 MHz		
Number of Channels	79		
Carrier Frequency of Each Channel	2402+n*1 MHz; n=0~78  Bluetooth BR(1Mbps) : 15.62 dBm (0.0365 W) Bluetooth EDR (2Mbps) : 15.19 dBm (0.0330 W)		
Maximum Output Power to Antenna	` ' '		
Antenna Type / Gain	Fixed Internal Antenna type with gain -2.00 dBi		
Type of Modulation	Bluetooth BR (1Mbps) : GFSK Bluetooth EDR (2Mbps) : $\pi$ /4-DQPSK Bluetooth EDR (3Mbps) : 8-DPSK		

### 1.5 Modification of EUT

No modifications are made to the EUT during all test items.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : 6 of 17
Report Issued Date : May 19, 2017
Report Version : Rev. 01

Report No.: FR733129-04A

### 1.6 Testing Location

Sporton Lab is accredited to ISO 17025 by Taiwan Accreditation Foundation (TAF code: 1190) and the FCC designation No. TW0007 under the FCC 2.948(e) by Mutual Recognition Agreement (MRA) in FCC Test.

Test Site	SPORTON INTERNATIONAL INC.	
	No. 52, Hwa Ya 1 <sup>st</sup> Rd., Hwa Ya Technology Park,	
Test Site Location	Kwei-Shan District, Tao Yuan City, Taiwan, R.O.C.	
rest Site Location	TEL: +886-3-327-3456	
	FAX: +886-3-328-4978	
Test Site No.	Sporton Site No.	
rest site No.	TH05-HY	

Note: The test site complies with ANSI C63.4 2014 requirement.

Test Site	SPORTON INTERNATIONAL INC.	
	No.58, Aly. 75, Ln. 564, Wenhua 3rd Rd. Guishan Dist,	
Toot Site Leastian	Taoyuan City, Taiwan (R.O.C.)	
Test Site Location	TEL: +886-3-327-0868	
	FAX: +886-3-327-0855	
Test Site No.	Sporton Site No.	
Test Site NO.	03CH11-HY	

Note: The test site complies with ANSI C63.4 2014 requirement.

# 1.7 Applicable Standards

According to the specifications of the manufacturer, the EUT must comply with the requirements of the following standards:

- FCC Part 15 Subpart C §15.247
- ANSI C63.10-2013

#### Remark:

- All test items were verified and recorded according to the standards and without any deviation during the test.
- 2. This EUT has also been tested and complied with the requirements of FCC Part 15, Subpart B, recorded in a separate test report.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : 7 of 17
Report Issued Date : May 19, 2017
Report Version : Rev. 01

Report No.: FR733129-04A

# 2 Test Configuration of Equipment Under Test

# 2.1 Carrier Frequency Channel

Frequency Band	Channel	Freq. (MHz)	Channel	Freq. (MHz)	Channel	Freq. (MHz)
	0	2402	27	2429	54	2456
	1	2403	28	2430	55	2457
	2	2404	29	2431	56	2458
	3	2405	30	2432	57	2459
	4	2406	31	2433	58	2460
	5	2407	32	2434	59	2461
	6	2408	33	2435	60	2462
	7	2409	34	2436	61	2463
	8	2410	35	2437	62	2464
	9	2411	36	2438	63	2465
	10	2412	37	2439	64	2466
	11	2413	38	2440	65	2467
	12	2414	39	2441	66	2468
2400-2483.5 MHz	13	2415	40	2442	67	2469
	14	2416	41	2443	68	2470
	15	2417	42	2444	69	2471
	16	2418	43	2445	70	2472
	17	2419	44	2446	71	2473
	18	2420	45	2447	72	2474
	19	2421	46	2448	73	2475
	20	2422	47	2449	74	2476
	21	2423	48	2450	75	2477
	22	2424	49	2451	76	2478
	23	2425	50	2452	77	2479
	24	2426	51	2453	78	2480
	25	2427	52	2454	-	-
	26	2428	53	2455	-	-

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : 8 of 17
Report Issued Date : May 19, 2017
Report Version : Rev. 01

Report No.: FR733129-04A

### 2.2 Descriptions of Test Mode

Preliminary tests were performed in different data rates and recorded the RF output power in the following table:

		Bluetooth RF Output Power  Data Rate / Modulation			
Channal	Eroguenev				
Channel	Frequency	GFSK	π/4-DQPSK	8-DPSK	
		1Mbps	2Mbps	3Mbps	
Ch00	2402MHz	<mark>15.62</mark> dBm	12.28 dBm	12.53 dBm	
Ch39	2441MHz	15.16 dBm	15.19 dBm	15.23 dBm	
Ch78	2480MHz	14.53 dBm	11.56 dBm	11.86 dBm	

a. The EUT has been associated with peripherals and configuration operated in a manner tended to maximize its emission characteristics in a typical application. Frequency range investigated: radiation (9 kHz to the 10th harmonic of the highest fundamental frequency or to 40 GHz, whichever is lower). Pre-scanned tests, X, Y, Z in three orthogonal panels, and different data rates were conducted to determine the final configuration (Z plane as worst plane) from all possible combinations, and the worst mode of radiated spurious emissions is Bluetooth 1Mbps mode, and recorded in this report.

#### 2.3 Test Mode

The following summary table is showing all test modes to demonstrate in compliance with the standard.

	Summary table of Test Cases		
Test Item	Data Rate / Modulation		
rest item	Bluetooth BR 1Mbps GFSK		
Radiated Test Cases	Mode 1: CH78_2480 MHz		
Remark: All the radiated test cases were performance with Adapter 1 and Battery 2.			


SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : 9 of 17
Report Issued Date : May 19, 2017
Report Version : Rev. 01

Report No.: FR733129-04A

# 2.4 Connection Diagram of Test System

<Bluetooth Tx Mode>



# 2.5 Support Unit used in test configuration and system

lt	em	Equipment	Trade Name	Model Name	FCC ID	Data Cable	Power Cord
1	۱.	Bluetooth Base Station	R&S	CBT32	N/A	N/A	Unshielded, 1.8 m

# 2.6 EUT Operation Test Setup

The RF test items, programmed RF utility, "WCN3990\_bt\_classic\_testmode.bat" installed in the notebook make the EUT get into the engineering modes to contact with Bluetooth base station for continuous transmitting and receiving signals

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : 10 of 17
Report Issued Date : May 19, 2017
Report Version : Rev. 01

Report No.: FR733129-04A

### 3 Test Result

## 3.1 Radiated Band Edges and Spurious Emission Measurement

#### 3.1.1 Limit of Radiated Band Edges and Spurious Emission

In any 100 kHz bandwidth outside the intentional radiator frequency band, all harmonics/spurious must be at least 20 dB below the highest emission level within the authorized band. In addition, radiated emissions which fall in the restricted bands must also comply with the limits as below.

Frequency	Field Strength	Measurement Distance
(MHz)	(microvolts/meter)	(meters)
0.009 - 0.490	2400/F(kHz)	300
0.490 - 1.705	24000/F(kHz)	30
1.705 – 30.0	30	30
30 – 88	100	3
88 – 216	150	3
216 - 960	200	3
Above 960	500	3

#### 3.1.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : 11 of 17
Report Issued Date : May 19, 2017
Report Version : Rev. 01

Report No.: FR733129-04A

#### 3.1.3 Test Procedures

- 1. The EUT was placed on a turntable with 0.8 meter for frequency below 1GHz and 1.5 meter for frequency above 1GHz respectively above ground.
- 2. The EUT was set 3 meters from the interference receiving antenna, which was mounted on the top of a variable height antenna tower.
- 3. For each suspected emission, the EUT was arranged to its worst case and then tune the Antenna tower (from 1 m to 4 m) and turntable (from 0 degree to 360 degrees) to find the maximum reading. A pre-amp and a high pass filter are used for the test in order to get better signal level to comply with the guidelines.
- 4. Set to the maximum power setting and enable the EUT transmit continuously.
- 5. Use the following spectrum analyzer settings:
  - (1) Span shall wide enough to fully capture the emission being measured;
  - (2) Set RBW=100 kHz for f < 1 GHz, RBW=1MHz for f>1GHz; VBW ≥ RBW; Sweep = auto; Detector function = peak; Trace = max hold for peak
  - (3) For average measurement: use duty cycle correction factor method per 15.35(c).

Duty cycle = On time/100 milliseconds

On time =  $N_1*L_1+N_2*L_2+...+N_{n-1}*LN_{n-1}+N_n*L_n$ 

Where  $N_1$  is number of type 1 pulses,  $L_1$  is length of type 1 pulses, etc.


Average Emission Level = Peak Emission Level + 20\*log(Duty cycle)

- 6. Corrected Reading: Antenna Factor + Cable Loss + Read Level Preamp Factor = Level.
- 7. For testing below 1GHz, if the emission level of the EUT in peak mode was 3 dB lower than the limit specified, then peak values of EUT will be reported, otherwise, the emissions will be repeated one by one using the CISPR quasi-peak method and reported.
- 8. For testing above 1GHz, the emission level of the EUT in peak mode was 20dB lower than average limit (that means the emission level in average mode also complies with the limit in average mode), then peak values of EUT will be reported, otherwise, the emissions will be measured in average mode again and reported.


Note: The average levels were calculated from the peak level corrected with duty cycle correction factor (24.79dB) derived from 20log (dwell time/100ms). This correction is only for signals that hop with the fundamental signal, such as band-edge and harmonic. Other spurious signals that are independent of the hopping signal would not use this correction.

#### 3.1.4 Test Setup

#### For radiated emissions below 30MHz



#### For radiated emissions from 30MHz to 1GHz




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : 13 of 17
Report Issued Date : May 19, 2017
Report Version : Rev. 01

Report No.: FR733129-04A

#### For radiated emissions above 1GHz



### 3.1.5 Test Results of Radiated Spurious Emissions (9 kHz ~ 30 MHz)

The low frequency, which started from 9 kHz to 30MHz, was pre-scanned and the result which was 20dB lower than the limit line was not reported.

#### 3.1.6 Test Result of Radiated Spurious at Band Edges

Please refer to Appendix A and B.

#### 3.1.7 Duty Cycle

Please refer to Appendix C.

# 3.1.8 Test Result of Radiated Spurious Emission (30MHz ~ 10<sup>th</sup> Harmonic)

Please refer to Appendix A and B.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : 14 of 17
Report Issued Date : May 19, 2017
Report Version : Rev. 01

Report No.: FR733129-04A

### 3.2 Antenna Requirements

#### 3.2.1 Standard Applicable

If directional gain of transmitting antennas is greater than 6dBi, the power shall be reduced by the same level in dB comparing to gain minus 6dBi. The use of a permanently attached antenna or of an antenna that uses a unique coupling to the intentional radiator shall be considered sufficient to comply with the FCC rule.

### 3.2.2 Antenna Anti-Replacement Construction

An embedded-in antenna design is used.

#### 3.2.3 Antenna Gain

The antenna peak gain of EUT is less than 6 dBi. Therefore, it is not necessary to reduce maximum peak output power limit.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : 15 of 17
Report Issued Date : May 19, 2017
Report Version : Rev. 01

Report No.: FR733129-04A

# 4 List of Measuring Equipment

Instrument	Manufacturer	Model No.	Serial No.	Characteristics	Calibration Date	Test Date	Due Date	Remark
Power Meter	Agilent	E4416A	GB412923 44	300MHz~40GH z	Dec. 26, 2016	Apr. 28, 2017	Dec. 25, 2017	Conducted (TH05-HY)
Power Sensor	Agilent	E9327A	US404415 48	300MHz~40GH z	Dec. 26, 2016	Apr. 28, 2017	Dec. 25, 2017	Conducted (TH05-HY)
Amplifier	SONOMA	310N	187312	9kHz~1GHz	Nov. 10, 2016	Apr. 27, 2017~ Apr. 29, 2017	Nov. 09, 2017	Radiation (03CH11-HY)
Loop Antenna	Rohde & Schwarz	HFH2-Z2	100315	9 kHz~30 MHz	Sep. 02, 2015	Apr. 27, 2017~ Apr. 29, 2017	Sep. 01, 2017	Radiation (03CH11-HY)
Bilog Antenna	TESEQ	CBL 6111D	35414	30MHz~1GHz	Oct. 15, 2016	Apr. 27, 2017~ Apr. 29, 2017	Oct. 14, 2017	Radiation (03CH11-HY)
Horn Antenna	SCHWARZBE CK	BBHA 9120 D	9120D-132 6	1GHz ~ 18GHz	Oct. 07, 2016	Apr. 27, 2017~ Apr. 29, 2017	Oct. 06, 2017	Radiation (03CH11-HY)
Preamplifier	Keysight	83017A	MY532700 80	1GHz~26.5GHz	Nov. 10, 2016	Apr. 27, 2017~ Apr. 29, 2017	Nov. 09, 2017	Radiation (03CH11-HY)
Spectrum Analyzer	Keysight	N9010A	MY542004 86	10Hz ~ 44GHz	Oct. 12, 2016	Apr. 27, 2017~ Apr. 29, 2017	Oct. 11, 2017	Radiation (03CH11-HY)
Antenna Mast	EMEC	AM-BS-4500- B	N/A	1~4m	N/A	Apr. 27, 2017~ Apr. 29, 2017	N/A	Radiation (03CH11-HY)
Turn Table	EMEC	TT 2000	N/A	0~360 Degree	N/A	Apr. 27, 2017~ Apr. 29, 2017	N/A	Radiation (03CH11-HY)
Preamplifier	MITEQ	AMF-7D-0010 1800-30-10P	1815698	1GHz~18GHz	Dec. 01, 2016	Apr. 27, 2017~ Apr. 29, 2017	Nov. 30, 2017	Radiation (03CH11-HY)
SHF-EHF Horn Antenna	SCHWARZBE CK	BBHA 9170	BBHA9170 584	18GHz- 40GHz	Nov. 08, 2016	Apr. 27, 2017~ Apr. 29, 2017	Nov. 07, 2017	Radiation (03CH11-HY)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : 16 of 17
Report Issued Date : May 19, 2017
Report Version : Rev. 01

Report No. : FR733129-04A

# 5 Uncertainty of Evaluation

#### **Uncertainty of Radiated Emission Measurement (30 MHz ~ 1000 MHz)**

Measuring Uncertainty for a Level of Confidence	5.2
of 95% (U = 2Uc(y))	J.Z

#### Uncertainty of Radiated Emission Measurement (1000 MHz ~ 18000 MHz)

Measuring Uncertainty for a Level of Confidence	
of 95% (U = 2Uc(y))	5.5

#### Uncertainty of Radiated Emission Measurement (18000 MHz ~ 40000 MHz)

Measuring Uncertainty for a Level of Confidence	5.2
of 95% (U = 2Uc(y))	3.2

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : 17 of 17
Report Issued Date : May 19, 2017
Report Version : Rev. 01

Report No.: FR733129-04A

# Appendix A. Radiated Spurious Emission

Test Engineer :	JC Liao, Jacky Hung, and Ken Wu	Temperature :	20~24°C
rest Engineer .		Relative Humidity :	50~54%

#### 2.4GHz 2400~2483.5MHz

#### BT (Band Edge @ 3m)

вт	Note	Frequency	Level	Over	Limit	Read	Antenna	Cable	Preamp	Ant	Table	Peak	Pol.
		( MHz )	( dBµV/m )	Limit (dB)	Line ( dBµV/m )	Level ( dBµV )	Factor ( dB/m )	Loss (dB)	Factor (dB)	Pos (cm)	Pos (deg)	Avg. (P/A)	
	*	2480	104.76	-	-	104.82	27.14	6.38	33.58	321	128	Р	Н
	*	2480	79.97	-	-	-	-	-	-	-	-	Α	Н
		2483.56	52.96	-21.04	74	53.01	27.14	6.39	33.58	321	128	Р	Н
		2483.56	28.17	-25.83	54	-	-	-	-	-	-	Α	Н
													Н
BT													Н
CH 78 2480MHz	*	2480	108.88	-	-	108.94	27.14	6.38	33.58	106	299	Р	V
240UNITZ	*	2480	84.09	-	-	-	-	-	-	-	-	Α	V
		2483.5	56.13	-17.87	74	56.18	27.14	6.39	33.58	106	299	Р	V
		2483.5	31.34	-22.66	54	-	-	-	-	-	-	Α	V
													٧
													٧
Remark		o other spurio		st Peak	and Averag	je limit lin	e.						

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978

All results are PASS against Peak and Average limit line.

#### 2.4GHz 2400~2483.5MHz

### BT (Harmonic @ 3m)

ВТ	Note	Frequency	Level	Over	Limit	Read	Antenna	Cable	Preamp	Ant	Table	Peak	Pol.
				Limit	Line	Level	Factor	Loss	Factor	Pos	Pos	Avg.	
		(MHz)	( dBµV/m )	(dB)	(dBµV/m)	(dBµV)	( dB/m )	(dB)	( dB )	( cm )	( deg )	(P/A)	(H/V)
		4960	49.77	-24.23	74	72.33	31.84	9.79	64.63	100	0	Р	Н
вт		7440	44.54	-29.46	74	59.31	38.06	11.67	64.88	100	0	Р	Н
													Н
													Н
CH 78		4960	49.26	-24.74	74	71.82	31.84	9.79	64.63	100	0	Р	V
2480MHz		7440	44.4	-29.6	74	59.17	38.06	11.67	64.88	100	0	Р	V
													V
													V

### Remark

. No other spurious found.

2. All results are PASS against Peak and Average limit line.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number

: A2 of A5

# Emission below 1GHz

# 2.4GHz BT (LF)

вт	Note	Frequency	Level	Over	Limit	Read	Antenna	Cable	Preamp	Ant	Table	Peak	Pol.
				Limit	Line	Level	Factor	Loss	Factor	Pos	Pos	Avg.	
		(MHz)	( dBµV/m )	(dB)	( dBµV/m )	(dBµV)	( dB/m )	( dB )	( dB )	( cm )	( deg )	(P/A)	(H/V
		67.8	28.57	-11.43	40	47.86	12.12	1.06	32.49	100	0	Р	Н
		199.02	27.67	-15.83	43.5	43.36	14.92	1.72	32.39			Р	Н
		261.12	32.22	-13.78	46	42.73	19.75	2.04	32.38			Р	Н
		442.1	32.72	-13.28	46	39.26	23.07	2.7	32.35			Р	Н
		854.4	32.49	-13.51	46	31.28	29.29	3.67	31.9			Р	Н
		951	33.08	-12.92	46	29.46	30.82	3.82	31.19			Р	Н
													Н
													Н
													Н
													Н
													Н
2.4GHz													Н
BT		31.35	33.06	-6.94	40	41.01	23.84	0.68	32.49	100	0	Р	V
LF		114.24	23.14	-20.36	43.5	37.06	17.13	1.39	32.47			Р	V
		261.66	23.66	-22.34	46	34.22	19.7	2.04	32.38			Р	V
		436.5	28.66	-17.34	46	35.27	22.99	2.7	32.35			Р	V
		776	30.07	-15.93	46	30.35	28.32	3.5	32.25			Р	V
		951.7	34.03	-11.97	46	30.36	30.86	3.82	31.18			Р	V
													V
													V
													V
													V
													V
													V

Remark

1. No other spurious found.

2. All results are PASS against limit line.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number

: A3 of A5

### Note symbol

Report No. : FR733129-04A

*	Fundamental Frequency which can be ignored. However, the level of any
	unwanted emissions shall not exceed the level of the fundamental frequency.
!	Test result is <b>over limit</b> line.
P/A	Peak or Average
H/V	Horizontal or Vertical

**SPORTON INTERNATIONAL INC.** Page Number : A4 of A5

TEL: 886-3-327-3456 FAX: 886-3-328-4978

#### A calculation example for radiated spurious emission is shown as below:

Report No.: FR733129-04A

WIFI	Note	Frequency	Level	Over	Limit	Read	Antenna	Cable	Preamp	Ant	Table	Peak	Pol.
Ant.				Limit	Line	Level	Factor	Loss	Factor	Pos	Pos	Avg.	
1+2		(MHz)	( dBµV/m )	(dB)	(dBµV/m)	(dBµV)	( dB/m )	( dB )	( dB )	( cm )	(deg)	(P/A)	(H/V)
802.11b		2390	55.45	-18.55	74	54.51	32.22	4.58	35.86	103	308	Р	Н
CH 01													
2412MHz		2390	43.54	-10.46	54	42.6	32.22	4.58	35.86	103	308	Α	Н

1. Level( $dB\mu V/m$ ) =

Antenna Factor(dB/m) + Cable Loss(dB) + Read Level(dB $\mu$ V) - Preamp Factor(dB)

2. Over Limit(dB) = Level(dB $\mu$ V/m) – Limit Line(dB $\mu$ V/m)

#### For Peak Limit @ 2390MHz:

- 1. Level(dBµV/m)
- = Antenna Factor(dB/m) + Cable Loss(dB) + Read Level(dBµV) Preamp Factor(dB)
- $= 32.22(dB/m) + 4.58(dB) + 54.51(dB\mu V) 35.86 (dB)$
- $= 55.45 (dB\mu V/m)$
- 2. Over Limit(dB)
- = Level(dBµV/m) Limit Line(dBµV/m)
- $= 55.45(dB\mu V/m) 74(dB\mu V/m)$
- = -18.55(dB)

#### For Average Limit @ 2390MHz:

- 1. Level(dBµV/m)
- = Antenna Factor(dB/m) + Cable Loss(dB) + Read Level(dBµV) Preamp Factor(dB)
- $= 32.22(dB/m) + 4.58(dB) + 42.6(dB\mu V) 35.86 (dB)$
- $= 43.54 (dB\mu V/m)$
- 2. Over Limit(dB)
- = Level( $dB\mu V/m$ ) Limit Line( $dB\mu V/m$ )
- $= 43.54(dB\mu V/m) 54(dB\mu V/m)$
- = -10.46(dB)

Both peak and average measured complies with the limit line, so test result is "PASS".


SPORTON INTERNATIONAL INC. Page Number : A5 of A5

TEL: 886-3-327-3456 FAX: 886-3-328-4978

# **Appendix B. Radiated Spurious Emission Plots**


Test Engineer :	JC Liao, Jacky Hung, and Ken Wu	Temperature :	20~24°C
rest Engineer.	Joe Liab, Jacky Fluing, and Neil Wu	Relative Humidity :	50~54%

# 2.4GHz 2400~2483.5MHz BT (Band Edge @ 3m)



TEL: 886-3-327-3456 FAX: 886-3-328-4978






TEL: 886-3-327-3456 FAX: 886-3-328-4978


#### 2.4GHz 2400~2483.5MHz

### BT (Harmonic @ 3m)



TEL: 886-3-327-3456 FAX: 886-3-328-4978

# Emission below 1GHz 2.4GHz BT (LF)




TEL: 886-3-327-3456 FAX: 886-3-328-4978



Report No.: FR733129-04A

# Appendix C. Duty Cycle Plots

#### DH5 on time (One Pulse) Plot on Channel 39



#### on time (Count Pulses) Plot on Channel 39



#### Note:

- 1. Worst case Duty cycle = on time/100 milliseconds =  $2 \times 2.88 / 100 = 5.76 \%$
- 2. Worst case Duty cycle correction factor = 20\*log(Duty cycle) = -24.79 dB
- 3. **DH5** has the highest duty cycle worst case and is reported.



#### **Duty Cycle Correction Factor Consideration for AFH mode:**

Bluetooth normal hopping rate is 1600Hz and reduced to 800Hz in AFH mode; due to the reduced number of hopping frequencies, with the same packet configuration the dwell time in each channel frequency within 100msec period is longer in AFH mode than normal mode.

In AFH mode, the minimum hopping frequencies are 20, to get the longest dwell time DH5 packet is observed; the period to have DH5 packet completing one hopping sequence is

2.88 ms x 20 channels = 57.6 ms

There cannot be 2 complete hopping sequences within 100ms period, considering the random hopping behavior, maximum 2 hops can be possibly observed within the period. [100ms / 57.6ms] = 2 hops

Thus, the maximum possible ON time:

2.88 ms x 2 = 5.76 ms

Worst case Duty Cycle Correction factor, which is derived from the maximum possible ON time,

 $20 \times log(5.76 \text{ ms}/100\text{ms}) = -24.79 \text{ dB}$ 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978

# **Appendix D. Original Report**

Please refer to Sporton report number FR733129A.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: IHDT56WB2 Page Number : D1 of D1
Report Issued Date : May 19, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1