


3. Internal Photograph of EUT

Brand Name: Motorola; Model Name: XT1926-2, XT1926-3



Antenna 1: GSM/WCDMA/LTE Band 5 <Tx/Rx>


Antenna 2: LTE Band 7/38 <Tx/Rx>

Antenna 3: LTE Band 7/38 <Tx/Rx>


Antenna 4: WCDMA/LTE Band 5 <Rx>

The Antenna 1, Antenna 2 and Antenna 3 can't transmit simultaneously.

Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3






Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3



Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3



Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3



Brand Name: Motorola; Model Name: XT1926-2, XT1926-3



Brand Name: Motorola; Model Name: XT1926-2, XT1926-3



Brand Name: Motorola; Model Name: XT1926-2, XT1926-3



Antenna 1: GSM/WCDMA/LTE Band 5 <Tx/Rx>


Antenna 2: LTE Band 7/38 <Tx/Rx>

Antenna 3: LTE Band 7/38 <Tx/Rx>

Antenna 4: WCDMA/LTE Band 5 <Rx>

The Antenna 1, Antenna 2 and Antenna 3 can't transmit simultaneously.

Brand Name: Motorola; Model Name: XT1926-2, XT1926-3



Brand Name: Motorola; Model Name: XT1926-2, XT1926-3



Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3




Brand Name: Motorola; Model Name: XT1926-2, XT1926-3



Brand Name: Motorola; Model Name: XT1926-2, XT1926-3



Brand Name: Motorola; Model Name: XT1926-2, XT1926-3



Brand Name: Motorola; Model Name: XT1926-2, XT1926-3

