



EMC TEST SETUP PHOTOS




EMC Report #20067-1, AC Line - Part 15



EMC Report #20067-1, Part 15, PC Peripheral



EMC Report #20067-1, Antenna - Substitution



EMC Report #20067-1, Tx Radiated

MOTOROLA, INC. Portable Cellular Phone SAR Test Report Number: **19960-1F**

Appendix 6

**Photographs of the device under test
>> EXTRACTED FROM FCC EXHIBIT 11 (SAR Report) <<<**

MOTOROLA, INC. Portable Cellular Phone SAR Test Report Number: **19960-1F**



Figure 1. Front of Phone



Figure 2. Phone Open

MOTOROLA, INC. Portable Cellular Phone SAR Test Report Number: **19960-1F**



Figure 3. Back of Phone



Figure 4. Phone Against the Flat Phantom

MOTOROLA, INC. Portable Cellular Phone SAR Test Report Number: **19960-1F**



Figure 5. Phone Against the Head Phantom (Cheek Touch)




Figure 6. Phone Against the Head Phantom (15°Tilt)

MOTOROLA, INC. Portable Cellular Phone SAR Test Report Number: **19960-1F**



Figure 7. Front of Phone with Case VLV32



Figure 8. Phone Open with Case VLV32

MOTOROLA, INC. Portable Cellular Phone SAR Test Report Number: **19960-1F**



Figure 9. Back of Phone with Case VLV32



Figure 10. Back View: Case CHYN4647A

MOTOROLA, INC. Portable Cellular Phone SAR Test Report Number: **19960-1F**



Figure 11. Side View: Case CHYN4647A