

October 22, 1999

CORRECTION TO FORM 731

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, Maryland 21046

Re: Correction to Form 731

Details:

Please **delete** the third line entry in item 12. This equipment does **not** have NAMPS capability. The entry was made in error.

Item 12. EQUIPMENT SPECIFICATIONS: (See instructions)							
Frequency range in MHz		Rated RF power output in watts	Frequency tolerance		Emission designator (See 47 CFR § 2.201 and § 2.202)	Microprocessor Model Number	
824	849	3	0.00025	%	40K0F1D		
824	849	3	0.00025	%	40K0F8W		
824	849	3	0.0007	%	171 4F8W		

Contact Information:

Please contact me by telephone at (847) 523-6167, by facsimile at (847) 523-2350, or by e-mail (A.Bachler@motorola.com), if there are any further questions or additional information needed concerning this filing.

Regards,

Andrew J. Bachler
FCC Liaison
Cellular Subscriber Sector
600 N. U.S. Highway 45
Libertyville, IL 60048-5343