


MOTOROLA EMC TEST SETUP PHOTOS


(Pages 1 to 4)




Motorola EMC Report #19799-1, AC Line - Part 15



Motorola EMC Report #19799-1, Part 15, PC Peripheral



Motorola EMC Report #19799-1, Antenna - Substitution



Motorola EMC Report #19799-1, Tx Radiated

Appendix 6
(Pulled out of FCC Exhibit 11)
Photographs of the device under test
(RF Exposure Tests)



Figure 1. Front of Phone



Figure 2. Back of Phone



Figure 3. Phone Open



Figure 4. Cheek/Touch Position



Figure 5. Tilt Position



Figure 6. Push-to-Talk (25mm away)



Figure 7. Body Worn (15mm away)